

STUDER

PROFESSIONAL AUDIO EQUIPMENT

Service Information

Hardware Modification Kit
40/88 for A820 MCH

2" 20.050.820.60

1" 20.050.820.30

SI 120b/88 E

1. Application

The hardware modifications described hereunder must be performed on all A820 multi-track tape recorders 1" and 2" version with delivery from STI up to 14th June 1988.

Information about the currently effective software for the A820 MCH can be obtained with STUDER INTERNATIONAL AG. The software is contained in a separate software update kit.

Please note:

- Machines that are delivered after September 1988 are modified as per SI 120b/88. These machines are also equipped with 2 gas springs to hold back the chassis in tilt-up position, each gas spring having a pressure force of 250 N.
- When a STUDER TLS 4000 Synchronizer is used together with the A820 Multitrack, the A820 MCH Interface of the TLS 4000 has to be equipped with the software 1.812.968.22.
- 8 Channel Machines (1" transports): These machines must be equipped with the tape tension sensors 1.820.385.00 (left) and 1.820.386.00 (right).

2. Summary of hardware changes

- New move roller with extremely low tape slippage for precise tape counting/locating and more accurate reel size inertia detection.
- New tape lifter with high wear-resistant tape guiding surface.
- Enlarged clearance between pinch roller and capstan shaft prevents tape slippage in play-mode.
- New tacho-roller sensing concept gives more reliability in case of tacho sensor failure during operation.
- New stop-position, left-hand roller retracted and mechanical brakes activated, no tape-head contact.
- New edit-position, left-hand roller engaged and mechanical brakes inactive, tape-head contact.

3. Contents of the modification kits

Update kit for 2" transports order no. 20.050.820.60:

- 1 SI 120b/88 3rd Edition	10.85.6062
- 1 Move Roller	1.820.450.08
- 1 Lifter Pin 2"	1.820.129.00
- 1 Resistor 680 Ohm	57.11.4681
- 2 Common Suppression Adjust kit	1.820.878.00
- 3 label index .81	1.010.081.43

Update kit for 1" transports order no. 20.050.820.30:

- 1 SI 120b/88 3rd Edition	10.85.6062
- 1 Move Roller	1.820.440.08
- 1 Lifter Pin 1"	1.820.128.00
- 1 Resistor 680 Ohm	57.11.4681
- 2 Common Suppression Adjust kit	1.820.878.00
- 3 label index .81	1.010.081.43

4. Modification instructions4.1 Spooling Motor Drive Amplifier 1.820.875.00Modification:

1. Remove resistor R7
2. Install Common Suppression Adjust Kit 1.820.878.00 :
(see Schematics and Layout)
 - 2.1. Remove screw and mount the 12 mm - bolt.
 - 2.2. Solder the two pieces of wire into the holes on the additional print 1.820.878.00.
 - 2.3. Screw the additional print 1.820.878.00 onto the previously mounted bolt.
 - 2.4. Solder the two pieces of wire into the holes of R7.
Check for good connection.
3. Attach label index .81 (1.010.081.43).

Common Mode Adjustment:

1. Connect only flat cable connector P1 to Spooling Motor Drive Amplifier. (All other connectors are unplugged.)
2. Switch tape recorder ON.
3. Measure offset voltage at TP2 (TP1 = ground) and write down offset voltage (voltage is between +/- 60 mV.)
4. Switch tape recorder OFF.
5. Apply a DC-voltage of +26 Volt to J1, Pin 1 with reference to TP1 (ground).
Use for this purpose the +26 Volt on TP7 (TP3 = ground) of the Fuse/Supply Failure Detector 1.820.866.00.
Make therefore the cable connections indicated in Fig. 4.1 .
6. Switch tape recorder ON.
7. Measure offset voltage at TP2 (TP1 = ground).
Adjust with potentiometer R101 (10kohm) to the same offset voltage as measured under step 3 (tolerance +/- 10mV).
8. Switch tape recorder OFF.
9. Secure potentiometer with locking-paint.
10. Repeat steps 1 - 9 for the second Spooling Motor Drive Amplifier.

4.2 Power Fail Sense Board 1.820.869.00

Due to a production error, resistor R4 is not inserted in the power fail sense board. (see attached schematics)

Modification:

The resistor R4 must be inserted in all power fail sense boards in the existing A820 multi-track machines. The power fail sense board is located between the two spooling motors.

1. Tilt up the tape deck section for easy access.
2. Take out the Power Fail Sense Board 1.820.869.00.
(Layout 1.820.869.11)
3. Insert R4 680 Ohm (57.11.4681).
4. Put the Power Fail Sense Board back.

Component:

- 1 Resistor 680 Ohm (57.11.4681)

4.3 Motor Assembly Right 1.820.141.00

Insufficient stroke length of the pinch roller assembly may result in tape slippage.

Modification:

The clearance of the pressure spring has to be increased to 0.5 ... 1mm.

1. Tilt up tape transport and remove right-hand Motor Assembly 1.820.141.00.
2. With a diagonal cutter or other suitable tool, shorten the right hand side control cam 1.820.141.06 by 3mm at the point indicated on the attached drawing. (Fig. X.X)
3. Motor assembly right 1.820.141.00 changes to 1.820.141.81. Attach index label .81 (1.010.081.43).

Adjustment:

The modification necessitates a readjustment of the distance between the pinchroller shaft and the headblock plate.

Adjusting the distance between pinchroller shaft and headblock plate: (see Fig. 4.3)

1. Switch tape recorder OFF.
2. Remove pinch roller.
3. Insert allen key (3mm) into the hole [1] and turn the pinch roller assembly clockwise to the end stop (Play - Position).
4. Loosen locknut (opening between flats 7mm) [2] on the tie rod at the pinch unit and turn tie rod [3] until a distance of ca. 0.1mm between pinchroller shaft and headblock plate is obtained.
5. Retighten locknut and secure with locking paint.
6. Install pinch roller.

Checking the pinch roller force:

1. Switch tape recorder ON.
2. Press EDIT then PLAY (Pinch roller is now in PLAY - Position).
3. Unscrew fixing screw by a few turns [4].
4. Hook spring dynamometer 0 - 20N to the screw, and pull in the direction of the connecting line between the centers of the capstan shaft and the pinch roller. While pulling, lightly brake the pinch roller with your finger.
5. The spring dynamometer should indicate 1.2 - 1.3kp at the point where the pinch roller just lifts off the tape (and consequently stops).

Adjusting the pinching force:

If the above value is not attained, the pinch roller spring has to be readjusted.

1. Tilt recorder to service position.
2. Switch recorder to EDIT then PLAY.
3. The adjusting nut [5] (prevailing torque type nut, opening across flats 7mm) of the pinch unit is accessible through a hole in the cast chassis. Adjust until the requested value is attained.
4. Reinstall pinch roller cover after the adjustment.

Important Note:

For machines that are delivered after September 1988 and are equipped with a 4-section pinch roller, the following holds:

- These machines have a straight pinch roller shaft.
- The pinch roller pressure force is 0.9 - 1 kg.
- The distance between the pinch roller shaft and the capstan shaft should be 13.5 - 13.8 mm → It is factory adjusted !

4.4 Lifter Pin 1.820.124.00 2"/ 1.820.123.00 1"

1. Remove headblock cover and old lifter pin.
2. Replace old lifter pin by the new lifter pin 1.820.129.00 (2") or 1.820.128.00 (1").

Adjusting the lifter pin:



1. Load a tape.
2. Remove the headblock cover.
3. Switch recorder to EDIT. The tape must be separated from the capstan shaft by a few tenths of a millimeter. (the tape just does not touch the capstan shaft).
4. Should this not be the case, loosen the locknut (opening across flats 5,5 mm) and adjust screw (opening across flats 7 mm) to such a point where the tape just does not touch the capstan shaft in EDIT mode.
5. Retighten locknut.
6. Reinstall headblock cover.

4.5 Move Roller 1.820.450.04 2"/ 1.820.440.04 1"

1. Remove old move roller.
2. Replace old move roller by new move roller 1.820.450.08 (2") or 1.820.440.08 (1").
3. Check the tape transport and readjust if necessary. (see Service Information SI 110/87 or 115/88 or Manual 10.27.0663 section 3.3.15)


4.6 MPU Audio 1.820.782.xx

Insert Jumper in position 9 instead of position 8.
(see attached Lay-out)




Spooling Motor Drive Amplifier 1.820.875.81

Fig. 4.1. Common Mode Adjustment




- PWMPL-L1 7
- PWMPL-L2 8
- PWMPL-L3 11
- PWMPL-L4 12
- PWMPL-L5 16
- PWMPL-L6 15
- AV-ICLD 13
- AV-ICRD 14



- IC1 : 4076 CMOS CMOS Trigger
- IC2 : NE5532AN CBE
- Q1, Q3, Q5, Q7 : BC337 CBE Bottom view
- Q2, Q4, Q6, Q8 : BC327 CBE Bottom view
- Q9...Q12 : GDS Bottom view
- R76, 77, 10... 81 : 4,7 Ω
- C16, C19; C22...C25 : 0,8 µF MPC
- D1, D2, D3, D10 : 1N4148

0 28.3.88 IVA				
STUDER			A820 TAPE TRANSPORT SECTION	PAGE 1 OF 1
SPOOLING MOTOR DRIVE AMPLIFIER			SC	1.820.875.87





53.03.0167

53.03.0466

REMOVE R7
R7 auslöten



REMOVE SCREW
&
MOUNT THE
BOLT



Schilder 1.820.875-04 / 43.01.0108
aufgeklebt nach Fabrikationsmuster.

Norm-Nr.	53.03.0167	53.03.0466	1.820.875-11	1.820.330-01	1.820.330-02
DN-Bez.					
Abmessung					
Zugehörige Unterlagen	BV640 PL, BV632, BV652	Formelzeichen	Material	2:4	6.5.88
Erstellt von		Erstellt durch	Freigegeben	1988	1.0
STÜCKER RECHENSDREH ZÜRICH		SPOOLING MOTOR DRIVE AMPL. ESE		1.820.875-81	

POWER FAIL SENSE PCB A.820.00



POS. NO.	PART NO.	VALUE	SPECIFICATIONS / EQUIVALENT	MANUF.
B-----1	50-04-0507	1M 5%Z	1M 5%Z, mfr 502M	GI-Met
B-----2	50-04-1109	20 V Z	01Z 35-C20	ITT-Mot,Pho,Tho,Trf
B-----3	50-04-1110	0.2 V Z	02Z 35-C02	ITT-Mot,Pho,Tho,Trf
B-----4	50-04-1114	10 V Z	02Z 35-C10	ITT-Mot,Pho,Tho,Trf
B-----5	50-04-1114	10 V Z	02Z 35-C10	ITT-Mot,Pho,Tho,Trf
B-----6	50-04-0125	1M 4448		Ac-ITT,Pho,Ses,Trf
B-----7	50-04-1119	15 V Z	02Z 35-C15	ITT-Mot,Pho,Tho,Trf
B-----8	50-04-0507	1M 5%Z	1M 5%Z, mfr 502M	GI-Met
IC-----1	50-18-0100	LH 317 LZ		Mat,Mat
IC-----2	50-18-0108	LH 317 LZ		Mat,Mat
J-----1	54-25-0002		See note 1	
J-----2	54-25-0002		See note 1	
J-----3	54-25-0002		See note 1	
J-----4	54-25-0002		See note 1	
P-----1	50-02-0108	24 V DC	Ly 4	Duron
P-----2	54-14-2002		See note 2	
P-----3	54-14-2002		See note 2	
B-----1	50-03-0512	80 99 4	80V 93 B	Mat,SGS
B-----2	50-03-0340	0C 337-25		ITT-Mot,Pho,Sis
B-----3	50-03-0340	0C 337-25		ITT-Mot,Pho,Sis
B-----4	50-03-0340	0C 337-25		ITT-Mot,Pho,Sis
B-----5	50-03-0512	80 99 4	80V 93 B	Mat,SGS
B-----6	57-11-0009	04 Ohm	5% 10% 4 Watt	
B-----7	57-11-0331	330 Ohm	5%	
B-----8	57-11-0478	847 Ohm	5%	
B-----9	57-11-0481	640 Ohm	5%	
B-----10	57-11-0271	270 Ohm	5%	
B-----11	57-11-0471	470 Ohm	5%	
B-----12	57-11-0271	270 Ohm	5%	
B-----13	57-11-0132	1.5 400m	5%	
B-----14	57-11-0342	5.6 400m	5%	







POS. NO.	PART NO.	VALUE	SPECIFICATIONS / EQUIVALENT	MANUF.
B-----10	57-11-0103	10 400m	5%	
B-----11	57-11-0103	10 400m	5%	
B-----12	57-11-0342	5.6 400m	5%	
B-----13	57-11-0271	270 Ohm	5%	
B-----14	57-11-0471	470 Ohm	5%	
B-----15	57-11-0331	330 Ohm	5%	
B-----16	57-11-0480	04 Ohm	5%	
B-----17	57-11-0370	0.47 Ohm	10% 4 Watt	

Note 1 - Connector: 2 contacts: AMP Nr. 02606-3
 Note 2 - Connector: 26 contacts: Yamachi Nr. P4P-10-08-0055
 Burydy Nr. 046 9 Dia 000 65
 J4 Nr. 1614-0002 VL

MANUFACTURER: Gc=Fairchild; GI=General Instruments; ITT=Intermetel;
 Mat=Motorola; Mat=National; M=National Semiconductor;
 Pho=Philips; Ses=Seiscor; SCS=SGS/Atos; Sis=Siemens;
 Trf=Telefunken; Tho=Thomson

DATE 07/04/82

POWER FAIL SENSE PCB 1.820.869.00



12.2.87 ND			
POWER FAIL SENSE BOARD		1.820.869.00	PAGE 1 OF 1




Fig. 4.2.

Werkstoff	Norm-Nr.: 14.04.0207	Oberfläche	Güte:	Änderung					③
	DIN-Bez.: AlMgSi 1 F32		Beh.:		8.3.88	DM	Ally.	Ally.	②
	Abmessung: 0,6 mm				9.4.85	JH	JM	JM	①
Zugehörige Unterlagen:	Freimasstoleranz:	Maßstab:	Ausgabe	14.3.84	JH	JM	JM	①	
	± 0,1	1 : 1	Datum		Gez.	Gepr.	Ges.	Index	
Ersatz für: 5589-61	Ersetzt durch:			Kopie für:					
STUDER REGENSDORF ZÜRICH	Benennung: <i>Steuerscheibe rechts</i>			Nummer: 1.820.141-06					








Fig. 4.3.



MP UNIT AUDIO CONTROL PCB 1.820.782.20 ASY 1, GRP 21 ELM 21



INSERTED:
 JS 3, 4, 5, 6, 7, 8, 9, 14, 16, 17, 18, 19

Jumper must be inserted in position 9 !