Quick Reference Guide to Sony TC-755:

Page:

2 Stuck pinch roller problem
- the order of disassembling parts

3 Layout of bottom PBS's with calibration points



2. Stuck pinch roller problem – the order of disassembling parts



-disassemble in the given order
-then clean and grease
-reassemble

3. Bottom view of calibration pots.



-for calibration instructions see the Service Manual